



CAP.5 / CAP-1

12 Volt Capacitors

Installation:


CAP Installation:

- Mount CAP as close to the amplifier as possible.
- Maximum CAP-1 terminal torque is 50 inch lbs. or 6mm.
Maximum CAP.5 terminal torque is 20 inch lbs. or 1.6mm.
- Use heavy positive and negative cables with heavy duty 1/4 in. terminals for the CAP posts. *Do not drill through CAP body or block vent hole.*

- Be sure to observe proper polarity when connecting cables!
Reverse polarity connection will damage the CAP and void the warranty!

- Connect the ground terminal.

- Turn on the head unit and touch the audio system turn-on wire to the square touch pad on the top of the CAP. Voltage will climb as the CAP charges.



- After the charge voltage climbs to at least 8 volts, the trigger wire may be removed. Permanently connect turn-on wire to terminal marked "T".
- Connect cable from positive terminal on CAP to positive connection on amp. Connect negative cable from CAP to negative connection on amp.



CASCADE AUDIO ENGINEERING

PH: 541-389-6821 - FX: 541-389-5273

sales@cascadeaudio.com

www.cascadeaudio.com